

The Product Data Amendment series of documents is produced to provide basic details of changes to CML data publications.

## 1.0 Introduction

- 1.1 This document describes the changes made to the EV9910B and EV9920 EvKit user manual, Publication No: UM9910/5 May 2010 to produce the updated version: UM9910/6 September 2010.

## 2.0 Reference Document(s)

- 2.1 Product user manual: UM9910/6 September 2010.

## 3.0 Products Affected

- 3.1 EvKit EV9910B.

## 4.0 Additions and Alterations

- General:  
CMX991 TXQP and TXQN annotations are swapped on the CMX991/CMX992 datasheet, resolving a typographical error in the previous version.  
A consequence of this update is that the I and Q input connections should be swapped.  
See Section 6.5.3 (Table 12 Transmitter Possible Errors).  
(Page 38)